



		Specialist Oilfield Services K.S.C				SOS / QA / 10			
INSPECTION REPORT									
Job Number		JO-25-387			Report Number		JO-25-387-2-02		
Item Detail		37-1/2" Rotary Table			Inspection Date		13/05/2025		
Traceability		SN# 122			Procedure ref.		QIP-45 issue 01 Rev 04..		
Customer		IRE			Acceptance STD		--		
Inspection Stage									
As received	After blasting / cleaning	After Pre- machining / proof machining	After welding	After final machining	After heat treatment	Prior assembly	After testing	After painting / coating	Final Inspection
Inspection Details									
#	Part Detail	Observation					Recommendation / Remark		
1	37-1/2" Rotary Table Make : IDECO SN# 122	# Dismantling of parts on going					# Subjected to client		
NOTE: N/A : NOT AVILABLE / APPLICABLE									
PICTURES / SKETCH / DRAWING REFERENCE									
<div style="display: flex; flex-wrap: wrap;">     </div>									



Specialist Oilfield Services K.S.C

SOS / QA / 10

INSPECTION REPORT

Job Number	JO-25-387	Report Number	JO-25-387-2-02
Item Detail	37-1/2" Rotary Table	Inspection Date	13/05/2025
Traceability	SN# 122	Procedure ref.	QIP-45 issue 01 Rev 04..
Customer	IRE	Acceptance STD	--



Inspected By	Specialist Oilfield Services	Verified By	Specialist Oilfield Services
Name	Hasan Muhammed	Name	Arsath Allan
Date	13/05/2025	Date	13/05/2025
Signature		Signature	



Issue No. / Issue Date: 01 / 01.04.2024
Rev. No. / Rev. Date: 01 / 11.11.2024