

Customer :	INTERNATIONAL RIG AND EQUIPMENT LTD	PO No.	TS/612/807	Report No	PW/IRE/147/07/24/01
Address :	Rig/Well No	NA		Date	25 JUL 2024
	Specification	DS-1		Location	ITS HAMRIYAH BASE
	Procedure No	CAT 3-5		ITS Job No	I-0147-UAE-24

Inspection Performed	Visual Inspection	Black Light connection	Dimensional -	Visual Body Inspection	Others
----------------------	-------------------	------------------------	---------------	------------------------	--------

Tool Description			Pin									Box								
Sl. No.	Description	Length	Connection	Inside Diameter	Outside Diameter	Bevel Diameter	Pin Length	SRG Dia/Cyl Dia	SRG Width/ Nose Dia	Tong Space	Condition	Connection	Outside Diameter	Bevel Diameter	Counter Bore Diameter	C/B wall thickness/ C/B Depth	Bore Back Dia	Box length/ B/B Length	Fish Neck length	Condition
1613-0-001	36" OD HOLEOPENER	94-13/16	7-5/8 REG	3	10	9-1/2	5-3/16	—	—	41-1/2	OK	7-5/8 REG	9-1/2	8-13/16	7-1/16	11/16	—	—	23-1/2	OK



[Handwritten Signature]
Inspector SHIJESH A

Remarks : _____

- PS - Pitted Seal DT - Thread Damage GT - Galled Threads
- DS - Damaged Seal PT - Pitted Thread WT - Worn-out Threads