



PARKER DRILLING

INTERNATIONAL TUBULAR'S FZE




DS-1 TOOLS INSPECTION REPORT

Customer :	INTERNATIONAL RIG AND EQUIPMENT LTD	PO No.	NC/530/652/REV2	Report No	ITS/IR&E/036/4/21/001AR
Address :		Rig/Well No	NA	Date	25 MAY 2021
		Specification	DS-1	Location	ITS HAMRIYAH BASE
		Procedure No	CAT 3-5	ITS Job No	I-0036-UAE-21
Inspection Performed	Visual Inspection	Black Light connection	Dimensional	Visual Body Inspection	Full Body MPI
Tool Description		BOX			
Sl. No.	Description	Length	Connection	Inside Diameter	Bevel Diameter
1613-0-001	36" OD HOLEOPENER	94-13/16	7-5/8 REG	3	10
				Outside Diameter	Bevel Diameter
				10	9-1/2
		Pin Length	SRG Diameter	SRG Width	Tong Space
		5-3/16	—	—	41-1/2
		Condition	Condition	Condition	Condition
		OK	OK	OK	OK
		Counter Bore Diameter	Counter Bore Diameter	Counter Bore Diameter	Counter Bore Diameter
		7-1/16	7-1/16	7-1/16	7-1/16
		Bevel Diameter	Bevel Diameter	Bevel Diameter	Bevel Diameter
		8-13/16	8-13/16	8-13/16	8-13/16
		Outside Diameter	Outside Diameter	Outside Diameter	Outside Diameter
		9-1/2	9-1/2	9-1/2	9-1/2
		Connection	Connection	Connection	Connection
		7-5/8 REG	7-5/8 REG	7-5/8 REG	7-5/8 REG
		Bore Back Diameter	Bore Back Diameter	Bore Back Diameter	Bore Back Diameter
		—	—	—	—
		Bore Back Length	Bore Back Length	Bore Back Length	Bore Back Length
		—	—	—	—
		Tong Space	Tong Space	Tong Space	Tong Space
		23-1/2	23-1/2	23-1/2	23-1/2
		Condition	Condition	Condition	Condition
		OK	OK	OK	OK



Comments: The above mentioned item inspected and found ok at the time of inspection


SHIDHESH. A
 Inspector

PS - Pitted Seal DT - Thread Damage GT - Galled Threads
 DS - Damaged Seal PT - Pitted Thread WT - Worn-out Threads