

STATEMENT OF FACT

The repair or activity described herein was performed in accordance with the scope defined by the owner as stated in the Scope of Work field.
NOTE: THIS STATEMENT OF FACT (SoF) DOES NOT FULFILL THE REQUIREMENTS OF A CERTIFICATE OF CONFORMANCE (CoC), CERTIFICATE OF SERVICE (CoS), OR OTHER DOCUMENTATION VERIFYING PRODUCT DESIGN.

THIS STATEMENT
ISSUANCE DATE: 16/Oct/2023

TRACKER OR
NOV JOB NUMBER: NOV-2291874-FS-1

CUSTOMER
AND / OR RIG NAME:

CUSTOMER PURCHASE
ORDER NUMBER(S): 85007374

CERTIFYING AUTHORITY
OR THIRD-PARTY INSPECTOR(S): N/A

ITEM AND EQUIPMENT DETAILS

ITEM OR EQUIPMENT
DESCRIPTION: ROTARY TABLE IDECO LR 37.5-E

PART NUMBER: IDECO LR - 37.5-E

SERIAL NUMBER: 118

NOV performed condition assessment, witnessed Category III NDE and functionality verification of Rotary Table as per NOV standards and procedures.

Condition assessment done as per NOV DOC#D9D1005397-PRO-001, Rev 02.

Refer service report for detailed scope of work.

Condition assessment; RigDoc# 121941694
Category III NDE; RigDoc# 121925749

N/A

All documents submitted in this documentation pack are confidential between NOV and the recipient.

For, and on behalf of, NOV:

Print Name: MUDASSAR S. SHARIFF		Title: FIELD SERVICE ENGINEER	
Prepared By:	Signature: MUDASSAR S. SHARIFF	Digitally signed by MUDASSAR S. SHARIFF Date: 2023.10.16 10:35:36 +03'00'	Date: 16/Oct/2023 (dd/MMM/yyyy)
Print Name: DERRICK SALDANHA		Title: SERVICE MANAGER - KUWAIT	
Reviewed By:	Signature: Derrick Saldanha	Digitally signed by Derrick Saldanha Date: 2023.10.16 15:59:43 +03'00'	Date: 16/Oct/2023 (dd/MMM/yyyy)

