

NOV Kuwait for Repair and Maintenance of Light and Heavy Equipment KDIPA S.P.C, Al Ahmadi Corner Complex, Safat Code No. 13010, Al Ahmadi, Kuwait (Reg No: 405419)

STATEMENT OF FACT

The repair or activity described herein was performed in accordance with the scope defined by the owner as stated in the Scope of Work.

NOTE: THIS STATEMENT OF FACT (SoF) DOES NOT FULFILL THE REQUIREMENTS OF A CERTIFICATE OF CONFORMANCE (CoC), CERTIFICATE OF SERVICE (CoS), OR OTHER DOCUMENTATION VERIFYING PRODUCT DESIGN.

THIS STATEMENT
ISSUANCE DATE: 03/Mar/2023

TRACKER OR
NOV JOB NUMBER: NOV-2229204-FS-1

CUSTOMER
AND / OR RIG NAME:

CUSTOMER PURCHASE
ORDER NUMBER(S): 85004050

CERTIFYING AUTHORITY
OR THIRD-PARTY INSPECTOR(S): N/A

ITEM AND EQUIPMENT DETAILS

ITEM OR EQUIPMENT
DESCRIPTION: IDECO LR-37.5 ROTARY TABLE

PART NUMBER: 10251867-001

SERIAL NUMBER: 122

SCOPE OF WORK:

NOV FST performed Condition assessment, Category III inspection and function test of Rotary Table as per NOV standards and procedures.

Refer service report for detailed scope of work.

Condition assessment RigDoc# 120040792
Category III NDE RigDoc# 119819703

EXCLUSIONS:

N/A

All documents submitted in this documentation pack are confidential between NOV and the recipient.

For, and on behalf of, NOV:

Prepared By:	Print Name:	Rahul Pillai	Title:	Quality Engineer
	Signature:	Ramachandra Pillai, Rahul	Date:	29/Mar/2023
Reviewed By:	Print Name:	Derrick Saldanha	Title:	Service Manager -Kuwait
	Signature:	Saldanha, Derrick	Date:	29/Mar/2023

Digitally signed by
Ramachandran Pillai, Rahul
Date: 2023.03.29 16:40:45
+04'00'

Digitally signed by
Saldanha, Derrick
Date: 2023.03.29 16:40:55
+04'00'
